DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-025029 Address: 333 Burma Road **Date Inspected:** 23-Jun-2011

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes An Qing Xiang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component: OBG** Components

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector, Anand Upadhye was present during the times noted above for observations relative to the work being performed.

WELDING

This QA Inspector observed the following work in progress:

BAY 14

This QA Inspector observed ZPMC qualified welding personnel identified as 066758 perform welding by Shielded Metal Arc Welding (SMAW), on Sub Assembly part SA3416 stiffener plate to SA3416 of OBG Segment 14W. Weld joint is identified as SEG3020D-328/329. ZPMC Quality Control (QC) Inspector identified as Zhu Lin was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2112-FCM-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 068097 perform welding by Shielded Metal Arc Welding (SMAW), on Sub Assembly part SA3416 stiffener plate to Deck panel diaphragm weld of OBG Segment 14W. Weld joint is identified as SEG3020D-330. ZPMC Quality Control (QC) Inspector identified as Zhu Lin was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2213-Tc-U4b-FCM-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 068097 perform welding by Shielded

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Metal Arc Welding (SMAW), on Sub Assembly part SA3416 stiffener plate to SA3416 of OBG Segment 14W. Weld joint is identified as SEG3020D-331/332. ZPMC Quality Control (QC) Inspector identified as Zhu Lin was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2112-FCM-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 067942 perform welding by Shielded Metal Arc Welding (SMAW), on Sub Assembly part SA3416 stiffener plate to Deck panel diaphragm weld of OBG Segment 14W. Weld joint is identified as SEG3020D-333. ZPMC Quality Control (QC) Inspector identified as Zhu Lin was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2213-Tc-U4b-FCM-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 067942 perform welding by Shielded Metal Arc Welding (SMAW), on Sub Assembly part SA3416 stiffener plate to SA3416 of OBG Segment 14W. Weld joint is identified as SEG3020D-334/335. ZPMC Quality Control (QC) Inspector identified as Zhu Lin was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2112-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, phone: 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Upadhye,Anand	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer